


DuraStar Illuminator Mounting Instructions



When mounting the DuraStar Illuminator onto the Flat Glass Gage, the louvers must be pointed upward, and the blank area must be at the top of the illuminator.
(Correct mounting is as shown in the above pictures)

Questions? Contact a Reliance Applications Engineer at
RelianceAppEng@clark-reliance.com

Reliance®

A PRODUCT OF CLARK-RELIANCE